



Phantom Power
LED on solder side



GroupDIY
51X
REQUIRED

[silent:arts]
V672X-rev03
18 JUN 2017